


Rejuvenation Instructions

#512 – Cable Preparation – iUPR & SPR



This NRI covers the following:

- How to remove the connector.
- How to prepare the cable using the semi-con scorer, tool stop, and insulation stripper.
- How to remove corrosion.
- How to add wrap wire.

Trademarks: <http://www.novinium.com/trademarks/>

Patents: <http://www.novinium.com/patents/>



WARNING: It is dangerous working around energized high-voltage systems, pressurized systems, and chemicals. Always work in accordance to the Novinium Field Operations Safety Handbook (FOSH) or other local governing safety standards.

Table of Contents

Removing the Connector 2

- 1. Cable has sufficient slack. 2
- 2. Cable has insufficient slack. 2

Preparing the Cable..... 4

- 1. Square the connector..... 4
- 2. Use the template to adjust cutbacks. 5
- 3. Marking tape position..... 5
- 4. Remove corrosion. 6
- 5. Blockages..... 7
- 6. Prepare non-tinned aluminum connectors..... 7
- 7. Prepare the conductor..... 8
- 8. Add the wrap wire..... 8

Installing the Connector 9

Removing the Connector

- In SPR installations, the connector must be replaced to ensure maximum reliability with the IA.
- For iUPR installations, if the existing connector and cable preparation quality are satisfactory and meet IEEE® P1816™ requirements, the existing connector may be kept with the cutbacks modified per the non-extension, or standard templates.
- Under some additional circumstances, Engineering approval can be given to keep the existing connector. Contact Engineering to discuss.
- The removal process depends on if there is sufficient slack in the cable.

1. Cable has sufficient slack.

- Position cable cutters next to the last crimp in the old connector, over the un-crimped portion of the connector. This will preserve conductor length.
- Remove the old connector with a square cut.



Figure 1: Cut next to the bottom crimp.

2. Cable has insufficient slack.

- Retrieve the connector cut-off tool, also known as the lug splitter.
 - There are two varieties of lug splitters: a URD size and a feeder size.
 - Select the correct one for the application.



Figure 2: Lug splitter kit.



Figure 3: Lug splitter head.

- b. Position the cable cutters where the conductor strands end.
 - This is usually just after the “no-crimp” line on the connector.
 - This will preserve the maximum conductor length possible.



Figure 4: Cut the connector after the top crimp.

- c. Cut the old connector with a square cut.



Figure 5: Square cut on the connector.

- d. Insert the appropriately spaced blade block into the DMC tool head. There are three differently spaced blade blocks in each Lug Splitter kit.



Figure 6: Three stock lug splitter blade blocks.

- e. If a larger spacing is required, remove the blades and add the available shims between the blades and block.
 - The distance between the blades should be slightly larger than the strand bundle diameter.




Figure 7: Lug splitter tool kit.

- f. Taking care not to damage the conductor strands, press the blades into the connector.
- g. Once the blades have pierced through the connector body, retract the blades.
 - Longer connectors may need to be cut more than once.




Figure 8: Blades piercing connector.

- h. Use two channel locks to split open the cuts and remove the connector.



Figure 9: Pull the cut connector apart.



Figure 10: Remove the connector pieces.

Preparing the Cable

1. Square the connector.

Use a square to check the quality of the conductor cut.

- The longest strand may not be more than:
 - 1/16" longer than the shortest strand for 7 to 19 strand conductors.
 - 1/8" longer than the shortest strand for conductors with more than 19 strands.
- Making the strands have a uniform length ensures full insertion of the conductor into the connector and a good electrical connection.
- Shorten the longer strands with a file or hacksaw to meet the specification.



Figure 11: Square the conductor strands.

2. Use the template to adjust cutbacks.

- a. Remove the cable jacket, if present, as necessary for cable preparation.
- b. Use the designated template to mark the new location of insulation and semi-con cutbacks per **NRI 500**.
- c. Adjust the semi-con cutback by using IEEE® P1816™ approved methods.
- d. Place the tool stop on the position called out on the template.
- e. Face the rounded shoulder of the tool stop away from the cable end.
- f. Tighten the tool stop to hand tight; then with a wrench, tighten a quarter to half turn more.
 - Do not overtighten as the tool stop can deform the insulation.



Figure 12: Adjust the semi-con layer per the template.

- g. Use only the Novinium mod 2 of the Speed Systems® Mark 1 insulation stripper to remove the insulation.
- h. Spiral cut the insulation until the stripper contacts the tool stop.
- i. Hold the tool stop from below to give the tool stop extra support.
- j. Take care not to cut or nick the strands. If the strands are damaged, cut the portion off and start over.
- k. Remove the tool stop when finished.
- l. Check for and smooth out any scratches or gouges made to the cable during this process. Otherwise, remove the damaged section and start preparation over.
- m. Check the cutbacks against the template and make any adjustments necessary.
- n. Clean the cable according to manufacturer's instructions.



Figure 13: Remove the insulation per the template.

3. Marking tape position.

Marking tape is placed on the cable to help with component alignment.

- a. Use a silver marker to mark the positions of the marking tape noted on the template.

- b. Place marking tape at the marks. If using molded components, tape can be placed after components are in their final positions, and the silver marks can be used until then.
 - This is done to avoid the tapes from sliding during positioning of the component body.
- c. For molded splices, mark a third marking tape position one splice body length from the insulation cutback on the cable that will hold the splice body during swaging and crimping.




Figure 14: Place cable against the template to physically compare.

4. Remove corrosion.

Removing corrosion from the conductor will increase conductivity, lower operating temperature, and help increase the lifespan of the connection.

- a. Using your fingers or a dental pick, separate a single strand from the outer bundle layer.
- b. Inspect the conductor for corrosion. The color can range from blue-green to white.

Copper conductors with no corrosion:

- Clean the outer strand layer with solvent and a wire brush.

Aluminum and copper conductors with corrosion:

- Gently fan the outer strand layer.
- Clean the strands with solvent and a rag.
- Use a dental pick or wire brush to remove any grease or oxides not removed by the solvent.



Figure 15: Fan the outer strands and remove grease or oxides.

Heavily corroded conductors:

- The most effective corrosion removal method is to individually abrade each corroded strand with 120 grit aluminum oxide sandpaper.
- Sanding the outer two strand layers and the outer surface of the remaining bundle drastically increases conductivity.
- In situations with extreme corrosion, every strand may need sanding.

- Protect the insulation from conductive particles. Do not damage the conductor.




Figure 16: Sand heavily corroded conductors.



Figure 17: Protect insulation from debris.

5. Blockages.

- If there is strand blocking compound, **STOP**. The cable cannot be injected.
- If there is a large amount of debris in the strands appearing to extend past the insulation cutback, call Engineering for troubleshooting options.



Figure 18: Strand blocked cable cannot be injected.

6. Prepare non-tinned aluminum connectors.

- a. Insert a wire brush into the connector's barrel to coat it with anti-oxidant grease.
- b. Scrape the inside of the barrel to remove the oxide layer and to spread the grease.



Figure 19: Scrape non-tinned aluminum connectors before use.

7. Prepare the conductor.

- a. With the same grease covered wire brush, scrape the thin oxide layer (or patina) from all exposed strands.
 - This will apply a coating of anti-oxidant grease to the strands making the electrical connection.
- b. Keep the half inch of strand length next to the insulation cutback free of grease.



Figure 20: Coat the conductor with grease from the connector.

8. Add the wrap wire.

There is a high flow resistance when injecting conductors with fewer than 34 strands. Adding a wrap wire to the conductor will help improve flow in and out of the space between strands (conductor interstices).

- a. Use some 20 ga. (0.032" diameter) wire of the same metal as the conductor.
- b. Wrap two to three revolutions of wire around the inner strand bundle (all except the outermost layer).



Figure 21: Wrap wires.



Figure 22: 2-3 wraps of wire around inner bundle.

- c. Slide the wire as close as possible to the insulation cutback.
- d. Return the strands to their original position, but they do not need to be coiled around as they originally were.
 - Using fingers is usually sufficient.




Figure 23: Return strands to original position.

- e. Apply a tight cinch or insert the strand bundle into the connector to “train” the strands into position.
- f. Remove the connector – it will be installed later.
- g. Remove the cinch, if used.




Figure 24: Train the strands with a cinch or connector.

Installing the Connector

To complete the connector installation for iUPR and SPR injections, follow procedures for the application:

- **NRI 522: 200A Elbows – iUPR**
- **NRI 523: 200A Elbows – SPR**
- **NRI 532: 200A Splices – iUPR**
- **NRI 533: 200A Splices – SPR**
- **NRI 542: 200A Live-Front Terminations – iUPR**
- **NRI 543: 200A Live-Front Terminations – SPR**
- **NRI 553: 600A Dead-Break Terminations – SPR**
- **NRI 563: 600A Live-Front Terminations – SPR**
- **NRI 573: 600A Splices – SPR**